



Condition Report

Lot # 2845160

Date: 12-9-11

Yard NSL YD# 49 Seller Regent Svc Claim/File# _____



Yr 2007 Make DUCA TI Model 1098 Trim Package Superbike Color Red

VIN 20MIXB EW27B001095 Keys (Y) N

Lic Plate # _____ Mileage 1941 Grade (circle one): 0 1 2 3 4 (5) = BEST!

1-212-261-1211

ENGINE <input type="checkbox"/> 4 CYL <input type="checkbox"/> TURBO <input type="checkbox"/> 6 CYL <input type="checkbox"/> DIESEL <input type="checkbox"/> 8 CYL <input checked="" type="checkbox"/> OTHER <input type="checkbox"/> 10 CYL <u>2 CYL.</u>		TRANSMISSION <input type="checkbox"/> AUTO <input checked="" type="checkbox"/> MANUAL <u>5</u> SPD. <input type="checkbox"/> ALL WHEEL DRIVE		POWER AND EQUIPMENT <input type="checkbox"/> STEERING <input type="checkbox"/> TILT <input type="checkbox"/> BRAKES <input type="checkbox"/> WINDOWS <input type="checkbox"/> A/C <input type="checkbox"/> LOCKS <input type="checkbox"/> CRUISE <input type="checkbox"/> SEATS		SAFETY <input type="checkbox"/> AIR BAG <input type="checkbox"/> PASSENGER AIR BAG <input type="checkbox"/> # _____ DEPLOYED		RADIO <input type="checkbox"/> AM/FM <input type="checkbox"/> C/D <input type="checkbox"/> CASSETTE <input type="checkbox"/> OTHER _____		INTERIOR <input type="checkbox"/> CLOTH <input type="checkbox"/> VINYL <input checked="" type="checkbox"/> LEATHER	
WHEELS/COVERS <input checked="" type="checkbox"/> STANDARD <input type="checkbox"/> WIRE <input type="checkbox"/> ALUM. ALLOY <input type="checkbox"/> OTHER _____		ROOF <input type="checkbox"/> MANUAL SUN ROOF <input type="checkbox"/> ELEC. SUN/MOON ROOF <input type="checkbox"/> T-TOPS <input type="checkbox"/> VINYL <input type="checkbox"/> ROADSTER		WAGONS / MINIVANS / VANS <input type="checkbox"/> ROOF RACK <input type="checkbox"/> CARGO <input type="checkbox"/> 15 PASS. <input type="checkbox"/> WOOD GRAIN <input type="checkbox"/> 5 PASS. <input type="checkbox"/> CUSTOMIZED <input type="checkbox"/> TOW PKG. <input type="checkbox"/> 7 PASS. <input type="checkbox"/> CUBE <input type="checkbox"/> THIRD SEAT <input type="checkbox"/> 12 PASS. <input type="checkbox"/> OTHER _____				PICKUPS / TRUCKS <input type="checkbox"/> 4X4 <input type="checkbox"/> VAN BODY <input type="checkbox"/> SHORT BED <input type="checkbox"/> LONG <input type="checkbox"/> STAKE BODY <input type="checkbox"/> DUAL REAR WHEELS <input type="checkbox"/> UTILITY <input type="checkbox"/> STEP BUMPER <input type="checkbox"/> BODY _____ FT. <input type="checkbox"/> TOW PKG. <input type="checkbox"/> OTHER _____			



PRE-LOSS CONDITION:		Damaged in Loss	PRE-LOSS CONDITION:		Damaged in Loss
Carpets:	<input type="checkbox"/> Good <input type="checkbox"/> Worn <input type="checkbox"/> Burn Holes <input type="checkbox"/> Stained	Y/N	Dash:	<input type="checkbox"/> Good <input type="checkbox"/> Worn / Cracked <input type="checkbox"/> Stained	Y/N
Seats:	<input checked="" type="checkbox"/> Good <input type="checkbox"/> Worn <input type="checkbox"/> Burn Holes <input type="checkbox"/> Stained	Y/N <u>(Y)</u>	Paint:	Good Y/N Faded Y/N Chips/Scratches # _____	Y/N
Headliner:	<input type="checkbox"/> Good <input type="checkbox"/> Worn <input type="checkbox"/> Burn Holes <input type="checkbox"/> Stained	Y/N	Tires:	Good <u>(Y)</u> / N Fair Y/N # Damaged in Loss _____	Y/N <u>(Y)</u>
Door Panels:	<input type="checkbox"/> Good <input type="checkbox"/> Worn <input type="checkbox"/> Burn Holes <input type="checkbox"/> Stained	Y/N	Windshield:	Good <u>(Y)</u> / N Chips Y/N Cracks Y/N	Y/N

Recommended Services: Shrink Wrap: Partial / Full Y/N Standard Cleanup Y/N
 Drive-Thru Sale Y/N Flood Cleanup Y/N

Comments: 2007 DUCATI SUPERBIKE
DAMAGE UPPER LEFT REAR BODY PANEL SHOWN IN LEFT REAR PIC. VIN + RUN + DRIVE VERIFIED CDS JLS

Prepared by: [Signature]